

Form No. 4: Summary of Recall Campaign in English (Related to Article 2)**Vehicle Safety/Pollution Recall Campaign in Japan**

Import Vehicles

Campaign No.	Gai-3320	Date	Nov. 30, 2021
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	The front passenger seats were manufactured by the seat supplier without the Occupancy Detection Sensor (ODS) . Where the ODS is not present, the vehicle will not warn the driver the passenger seat is occupied but the seat belt is not buckled. Install the Occupancy Detection Sensor properly.		

Type	Commercial name	Model year recalled	Number of vehicles
3AA-LR3UB	Discovery	2022	3
Total			3

(JIS A4 size)