

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic

CAMPAIGN No.	5067	DATE	December 2, 2021
MANUFACTURER	UD Trucks Corporation		
DESCRIPTION OF DEFECT	With regards to the vehicle manufacturing plant's delivery inspection procedure, due to the inappropriate delivery inspection management, the inspection regarding the safety regulations for road vehicles was not conducted appropriately.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-CG5CA	Quon	2021	4	
2PG-GK5AAB		2021	3	
			7	