VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

| | _ | | | |
|----------------|--|------|-----------|--|
| CAMPAIGN No. | Gai-3326 | DATE | 2021/12/2 | |
| MANUFACTURE | Mercedes-Benz AG | | | |
| | (Japanese Importer : Mercedes-Benz Japan Co,. Ltd.) | | | |
| DESCRIPTION OF | On certain S-Class vehicles (223 platform) with Diesel engine, the fuel level might not be | | | |
| DEFECT | displayed correctly. | | | |
| | Due to contact with an internal fuel line in the fuel tank, the movement of the fuel fill level | | | |
| | sensor might be impaired. As a consequence, the fuel display might indicate a higher fuel | | | |
| | level than what is actually remaining in the tank. In this situation, the vehicle might run out of | | | |
| | fuel without the driver being aware of it and subsequently the engine might stall during | | | |
| | driving. | | | |
| | This would increase the risk of a crash. | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

| TYPE | COMMERCIAL | MODEL YEAR | NUMBER OF |
|------------|--------------|------------|-----------|
| | NAME | RECALLED | VEHICLE |
| 3DA-223033 | S400d 4MATIC | 2021 | 107 |
| 3DA-223133 | | | 8 |
| | | TOTAL | 115 |