

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.		DATE	December 22, 2021
MANUFACTURE	Changzhou Yamasaki Motorcycle Co., Ltd. (Japanese Importer :AlivePlus CO., LTD)		
DESCRIPTION OF DEFECT	Some brake caliper fixing bolts have been tightened with excessive torque due to inappropriate work management during production. If the bolts are damaged and used continuously, they may loosen, and in the worst case, the caliper may fall off, resulting in loss of braking ability.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
	APtrikes125	2019-2021	1100
		TOTAL	1100