

第4号様式(英文リコール概要書) (第2関係)

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5081	DATE	2021/12/27
MANUFACTURER	Thinktogether,Inc.		
DESCRIPTION OF DEFECT	In the electric power steering mechanism, the evaluation at the time of design was insufficient, so if continue to use it as it is, the steering rod bracket will be damaged due to the unexpected output, the steering link will come off, and in the worst case, The steering wheel may not turn and may interfere with other traffic.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KUMITATE	eCOM-4	2021	1
		TOTAL	1

(日本工業規格A列4番)