

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3161	DATE	2021/1/28
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	<p>On certain C-Class (205 platform), GLC-Class (253 platform) and AMG GT (290 platform) Mercedes-AMG vehicles the software of the ESP control unit might not meet the specifications.</p> <p>In this case, the ESP system might not be adapted to the installed type of brake. Furthermore, in case of a potential drift of the yaw rate sensor or a failure of the brake negative pressure supply, the ESP system might not react as intended.</p> <p>This might lead to an ESP intervention that does not correspond to the driving situation. This would increase the risk of a crash or injuries.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-205086	Mercedes AMG C63	2019	23
		2020	2
CBA-205286	Mercedes AMG C63 SW	2019	6
		2020	1
CBA-205386	Mercedes AMG C63 coupe	2019	4
CBA-205087	Mercedes AMG C63S		165
CBA-205287	Mercedes AMG C63S SW	2019	54
		2020	1
CBA-205387	Mercedes AMG C63S coupe	2019	91
		2020	2
CBA-205487	Mercedes AMG C63S cabriolet	2019	49
4BA-253389	Mercedes AMG GLC63S 4MATIC+ coupe	2020	1
4AA-290659	Mercedes AMG GT43 4M+	2019	11
4AA-290659C	Mercedes AMG GT43 4MATIC+		19

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
4AA-290661	Mercedes AMG GT53S 4MATIC+	2019	173
		2020	22
4BA-290689	Mercedes AMG GT63S 4MATIC+	2019	300
		2020	14
		TOTAL	951