

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4885	DATE	Feb. 3. 2021
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain emission control devices, due to the inappropriate program of the engine control computer, the turbocharger does not transmit the failure diagnosis result to the engine control computer. Therefore, even if the turbocharger fails, the engine warning light is not illuminated.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2SG-XKC605M	[HINO Dutro]	2019~2020	63
2SG-XKU605M 2SG-XKU605X		2019~2020	111
2SG-XKU645M		2019	1
2SG-XKU655M		2019~2020	118
2SG-XKU702M		2019~2020	21
2SG-XKU710M		2019~2020	124
2SG-XKU712M		2019~2020	263
2SG-XKU722M		2019~2020	25
2RG-XZC600T		2019~2020	757
2PG-XZC605M 2RG-XZC605M		2019~2020	2,954
2RG-XZC630T		2019~2020	33
2RG-XZC645M		2019~2020	285
2RG-XZC655M		2019~2020	670
2KG-XZC675M 2KG-XZC675T		2019~2020	289
2RG-XZC710M		2019~2020	453
2PG-XZU600E 2RG-XZU600E 2RG-XZU600T 2RG-XZU600X		2019~2020	5,876
2PG-XZU602F		2019~2020	37
2PG-XZU605M 2RG-XZU605M 2RG-XZU605X		2019~2020	4,900
2RG-XZU630T		2019~2020	435
2RG-XZU640M		2019~2020	384

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-XZU642F 2PG-XZU642J	[HINO Dutro]	2019～2020	124	
2RG-XZU645M		2019～2020	832	
2RG-XZU650M		2019～2020	688	
2PG-XZU652F		2019～2020	287	
2PG-XZU655M 2RG-XZU655M		2019～2020	1,582	
2KG-XZU675M 2KG-XZU675T		2019～2020	1,702	
2KG-XZU685M		2019～2020	1,357	
2KG-XZU695M		2019～2020	451	
2RG-XZU700M		2019～2020	119	
2PG-XZU702M 2PG-XZU702X 2RG-XZU702M		2019～2020	230	
2RG-XZU710M		2019～2020	1,679	
2PG-XZU712M 2RG-XZU712M		2019～2020	2,833	
2RG-XZU720M		2019～2020	490	
2PG-XZU722M 2RG-XZU722M		2019～2020	1,452	
2KG-XZU775M		2019～2020	354	
2SG-XKC605		[Toyota Dyna200]	2019～2020	15
2SG-XKU605		[Toyota Dyna300]	2019～2020	14
2SG-XKU645		[Toyota Dyna400]	2019	1
2SG-XKU655		[Toyota ToyoaceG25]	2019～2020	9
2SG-XKU702		[Toyota ToyoaceG35]	2020	4
2SG-XKU710	[Toyota ToyoaceG45]	2019～2020	6	
2SG-XKU712		2019～2020	7	
2SG-XKU722		2019～2020	11	
2RG-XZC600D		2019～2020	164	
2PG-XZC605 2RG-XZC605		2019～2020	1,960	
2RG-XZC630D		2019～2020	16	
2RG-XZC645		2019～2020	159	
2RG-XZC655		2019～2020	131	
2KG-XZC675 2KG-XZC675D		2019～2020	196	
2RG-XZC710		2019～2020	118	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2RG-XZU600A	[Toyota Dyna200]	2019~2020	538
2RG-XZU600D	[Toyota Dyna300]		
2RG-XZU600H	[Toyota Dyna400]		
2PG-XZU602W	[Toyota ToyoaceG25]	2020	1
2PG-XZU605	[Toyota ToyoaceG35]	2019~2020	1,532
2RG-XZU605	[Toyota ToyoaceG45]		
2RG-XZU605A			
2RG-XZU630D		2019~2020	47
2RG-XZU640		2019~2020	74
2PG-XZU642W		2019~2020	2
2RG-XZU645		2019~2020	319
2RG-XZU650		2019~2020	74
2PG-XZU652W		2019~2020	8
2PG-XZU655		2019~2020	613
2RG-XZU655			
2KG-XZU675		2019~2020	315
2KG-XZU675D			
2KG-XZU685		2019~2020	228
2KG-XZU695		2019~2020	135
2RG-XZU700		2019~2020	48
2PG-XZU702		2019~2020	33
2PG-XZU702A			
2RG-XZU702			
2RG-XZU710		2019~2020	626
2PG-XZU712		2019~2020	309
2RG-XZU712			
2RG-XZU720		2019~2020	124
2PG-XZU722		2019~2020	364
2RG-XZU722			
2KG-XZU775		2019~2020	125
		TOTAL	40,305