

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3166	DATE	February 8th, 2021
MANUFACTURE	McLaren Automotive (Japanese Importer : McLaren Automotive Asia Pte Ltd.)		
DESCRIPTION OF DEFECT	In the noise, vibration and harshness (NVH) foam padding which is provided on the underside of the fuel tank, due to insufficient verification of moisture trapped in the NVH foam padding, once the NVH foam padding happens to take up water or moisture, in some cases, the NVH foam padding is left wet for a long period of time. As a result, with corrosive moisture, the fuel tank may corrode, leading to a risk of leakage of fuel from the fuel tank. If this is not addressed, there may be caused a risk of fire in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-P13GT	McLaren 570GT	2017 - 2019	35
ABA-P14S	McLaren 720S Coupe McLaren 720S Spider	2018 - 2020	124
ABA-P15S	McLaren Senna	2019	17
7BA-P22GT	McLaren GT	2020	20
		TOTAL	196