

Form No. 4: Summary of Recall Campaign in English (Related to Article 2)

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai-3172	Date	Feb. 16, 2021
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	<p>A concern has been identified with certain 2020 Model Year Range Rover Evoque and Discovery Sport vehicles built at the Halewood UK assembly plant, where due to an error in a service software update, the Instrument Cluster (IC) randomly displays alternating speedometer and odometer units between MPH and KM/H while the vehicle is in motion without the driver making any selection of display units.</p> <p>Retailers / Dealers will update the vehicles with the latest software.</p>		

Type	Commercial name	Model year recalled	Number of vehicles
3DA-LZ2NA	Range Rover Evoque	2020	19
5BA-LZ2XA			15
7BA-LZ2XAP			3
3DA-LC2NC	Discovery Sport		4
5BA-LC2XC			6
			Total

(JIS A4 size)