

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3175	DATE	18 th , Feb, 2021
MANUFACTURER	Automobili Lamborghini SpA (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	<p>On some of the affected vehicles, the integrity of the quick connector of the fuel line located in the engine compartment may be compromised. In rare instances high engine compartment temperatures subject the quick connectors to temperatures above the design operating specification limit.</p> <p>These elevated temperatures can lead to the quick connect material softening which could potentially result in a fuel leak.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-ZLDHU	URUS	2020	11