

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3178	DATE	2021/2/25
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On certain GLE, GLS (166 platform) and SL vehicles (231 platform) the software of the engine control unit might not meet the specification. In this case, in the driving programs S and S+ the reinstated speed after the propulsion shutdown may be applied too low, whereby the length and number of propulsion shutdown events could be higher than intended. Due to the resulting oxygen overflow, the conversion of NOx emissions within these driving programs could be reduced. As a result, NOx emissions could be increased and no longer meet local legal requirements.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-231474	Mercedes AMG SL63	2019	3
CBA-166074	Mercedes AMG GLE63S 4M C		1
CBA-166874	Mercedes AMG GLS63 4M		1
		TOTAL	5