

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4896	DATE	Feb.26 2021
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	Since the program is inappropriate in the vehicle controller of the crane vehicle, the vehicle may start moving if the PTO switch is operated while the parking brake is released.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
KA4120	—	2019~2020	11	
TOTAL			11	