

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai – 3206	DATE	12 April, 2021
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	There is a possibility that clamping nuts, on which the thread was not manufactured according to specifications, were fitted on various threaded connections on the chassis on the affected vehicles. As a result, the required tightening torque was reached before the threaded connection was actually tightened fully when fitting the clamping nuts. There is therefore no guarantee that the affected threaded connections will remain sufficiently tight over the service life of the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-982M20	718 Cayman	2021	3
	718 Cayman T	2021	1
3BA982M40	718 Boxster GTS 4.0	2021	1
3BA-992L30	911 Carrera	2021	5
	911 Carrera 4	2021	1
	911 Carrera S	2021	2
7BA-982L40	718 Cayman GT4	2021	6
	718 Spyder	2021	4
ZAA-J1MB	Taycan 4S	2021	1
ZAA-J1MD	Taycan Turbo S	2021	4
		Total	28