VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4940	DATE	April 21 ,2021
MANUFACTURER		ISUZU MOTORS LIMITED	
MANUFACTURER DESCRIPTION OF DEFECT		On certain emission control devices, due to the inappropriate diagnostic program of the control computer, some of the diagnoses or warning display may not be correct in the event of failure. As such, these emission control devices fail to comply with the technical requirements of attachment 48 of the detailed notification article 41 of the Safety Standard article 31, "On-board Diagnostic Device (Diesel Heavy-Duty Vehicle J-OBDII)".	

ТҮРЕ	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
2TG-RU1ASDJ	[ISUZU GALA]	2019-2020	171
2RG-RU1ESDJ		2019-2020	120
2DG-RU2AHDJ 2KG-RU2AHDJ		2019-2020	49
2DG-RR2AJDJ	[ISUZU GALA MIO]	2019-2020	163
2SG-HL2ANBD	[ISUZU ERGA]	2019	2
2SG-HL2ASBD		2019	2
		TOTAL	507