## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

			Domestic Import Vehicles	
CAMPAIGN No.	Gai-3211	DATE	2021/4/22	
MANUFACTURE	TURE Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co,. Ltd. )			
DESCRIPTION OF DEFECT	On certain A-Class (177 platform), GLA (247 platform) and CLA (118 platform) vehicles with			
	4-cylinder gasoline engine, the variant of the spark plugs might not meet specifications.			
	In this case, the combustion might be impaired and an exceedance of CO2-emissions and			
	exhaust gas emissions cannot be excluded.			
	Over a longer period of operating time, an increased mechanical wear of the spark plug due			
	to thermal overload could not be ruled out. As a result, parts of the spark plug might detach			
	in the combustion chamber, potenially leading to an engine damage. In this case, a stalling of			
	the vehicle cannot be ruled out. This would increase the risk of an accident.			

ТҮРЕ	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
4BA-177054M	Mercedes-AMG A45S 4MATIC+	2020	9
4BA-118354M	Mercedes-AMG CLA45S 4MATIC+		7
4BA-118654M	Mercedes-AMG CLA45S 4MATIC+	2020	1
	Shooting brake		
		TOTAL	17