

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3372	DATE	March 18th, 2022
MANUFACTURE	McLaren Automotive (Japanese Importer : McLaren Automotive Asia Pte Ltd.)		
DESCRIPTION OF DEFECT	There is a risk that the connection between the driver airbag and the occupant restraint controller may not been fully engaged, whereby the connector is connected but the secondary locking tab is not locked.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7BA-P22GT	McLaren GT	2019 - 2021	94
		TOTAL	94