

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5113	DATE	March 16, 2022
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	<p>①In a vibration damping material for the front of a cabin of an agricultural tractor, since the assembling work is inappropriate, a sound absorbing material is stuck on a protective film without peeling off an unnecessary protective film on the surface of the vibration damping material. Therefore, if the use is continued as it is, the sound absorbing material may come off together with the protective film and approach the muffler, and in the worst case, the sound absorbing material may be burned by the heat of the muffler, resulting in a fire.</p> <p>②In a wire harness in a engine room of a tractor for agricultural use, there is a case where the wire harness is worn by rubbing on a stay by vibration during running due to improper handling. If the product is continued to be used as it is, the coating of the wire harness may be damaged by wear and the internal electric wire may be short-circuited, and in the worst case, the wire harness may be burned and a fire may occur.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SB-MZD	「MZ50」	2009	16
	「MZ55」	2009	17
	「MZ60」	2009	21
SB-MZF	「MZ65」	2009	211
-	「MZ65-HPC」		
SB-MZF	「MZ70」	2009	3
SB-MZF	「MZ75」	2009	33
-	「MZ75-HPC」		
SB-MZG	「SMZ76」	2007~2010	644
-	「SMZ76-HPC」		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SB-MZG	「SMZ85」	2007～2010	308
-	「SMZ85-HPC」		
SB-MZG	「SMZ95」	2007～2010	869
-	「SMZ95-HPC」		
KDN-MZS	「MZ505」	2009～2014	189
	「MZ555」	2009～2014	437
	「MZ555-PC」		
	「MZ605」	2009～2014	540
KDN-MZX	「MZ655」	2009～2014	2,138
	「MZ655-PC」		
	「MZ705」	2009～2014	356
KDP-MZY	「MZ755」	2009～2014	1,086
	「MZ755-PC」		
KDP-MZZ	「SMZ805」	2010～2014	717
	「SMZ805-PC」		
	「SMZ875」	2010～2014	348
	「SMZ875-PC」		
	「SMZ875-AT」		
	「SMZ955」	2010～2014	1,777
	「SMZ955-PC」		
	「SMZ955-AT」		
SB-MZD	「GV500」	2009	5
	「GV550」	2009	6
	「GV600」	2009	12
SB-MZF	「GV650」	2009	22
-	「GVK650」		
SB-MZF	「GV700」	2009	1
SB-MZF	「GV750」	2009	15
-	「GVK750」		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SB-MZG	「GV760」	2007～2010	58
-	「GVK760」		
SB-MZG	「GV850」	2007～2010	34
-	「GVK850」		
SB-MZG	「GV950」	2007～2010	85
-	「GVK950」		
KDN-MZS	「GV505」	2009～2014	51
	「GV555」	2009～2014	62
	「GV605」	2009～2014	104
KDN-MZX	「GV655」	2009～2014	227
	「GVK655」		
	「GV705」	2009～2014	62

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDP-MZY	「GV755」	2009～2014	112
	「GVK755」		
KDP-MZZ	「GV805」	2010～2014	52
	「GVK805」		
	「GV875」	2010～2014	30
	「GVK875」		
	「GV955」	2010～2014	178
	「GVK955」		
SB-MZF	「2500MZ」	2009	33
KDN-MZX	「T2500MZ」	2009～2014	680
(TOTAL 7 TYPES)	(TOTAL 61 MODELS)	TOTAL	11,539

[Notes]

The range of vehicle numbers for recalled vehicles may include vehicles that are not.