VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

 CAMPAIGN No.
 Gai–3395
 DATE
 Apr 26 2022

 MANUFACTURE
 FCA US LLC (Japanese Importer : Stellantis Japan Ltd.)
 FCA US LLC

 DESCRIPTION OF DEFECT
 The second row seats may have been built with a missing weld or welds from the seat back frame to the child tether on one or both seats. Vehicles built with a missing weld from the seat back frame to the child tether may not meet regulatory strength requirement for tether anchorages. A tether anchorage separating completely from the vehicle seat may increase the risk of injury to the occupant of the child seat in a crash.

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|-----------|--------------------|------------------------|----------------------|
| 7BA-WL36L | 「Grand Cherokee L」 | 2022 | 3 |
| | | TOTAL | 3 |

Import Vehicles