

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 1 2 9	DATE	Apr. 14. 2022
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Regarding the vehicle control module for the e-POWER model, running out of fuel may be detected due to inappropriate control program, while driving on the specific road and driving condition with fuel remaining and starting the engine to generate electricity. Therefore, the vehicle may not be driven by fail-safe mode activated which stops the driving power.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DAA-HC27 6AA-HC27	N I S S A N S E R E N A	2 0 1 9 ~ 2 0 2 2	9, 236
DAA-HFC27 6AA-HFC27		69, 728	
		TOTAL	78, 964