

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	5155	DATE	May 31, 2022
MANUFACTURE	TOYOTA INDUSTRIES CORPORATION		
DESCRIPTION OF DEFECT	With the braking system of electronic forklift vehicles, the braking device that functions in the battery low voltage error condition may not operate due to improper program of the control unit, and there is a possibility that the vehicle can not be decelerated and stopped safely.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7FB45	TOYOTA GENEIO B	2011 - 2014	6
	TOYOTA FORKLIFT	2015 - 2021	23
		TOTAL	29