

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~(~~ Import Vehicles)

CAMPAIGN No.	Gai-3399	DATE	2022/5/25
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On certain CLA (118 platform), A-Class (177 platform), C-Class (205 platform), S-Class (222 platform), GLB (247 platform), CLS (257 platform), AMG GT 4-doors Coupe (290 platform) and G-Class (463 platform) vehicles with a gasoline engine, a particle in the fuel rail might lead to a leak between the fuel rail and the fuel injector. A trapped particle might damage the sealing between the fuel rail and fuel injector, whereby this impaired sealing might cause fuel to leak into the engine compartment. Leaking fuel at this position might come into contact with hot parts of the engine. Thus, a risk of a fire cannot be excluded. Furthermore, local legal requirements might not be met.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
5BA-177147M	A250 4MATIC Sedan	2019	1	
		2020	1	
4BA-177051M	Mercedes-AMG A35 4MATIC		1	
4BA-118651M	Mercedes-AMG CLA35 4MATIC Shooting Brake		1	
5BA-247647M	GLB250 4MATIC		1	
5BA-205076C	C180		1	
DBA-205240C	C180 Wagon		2	
DAA-257359	CLS450 4MATIC		2019	2
DAA-222058	S450		2020	1
ABA-463260	G550	2019	1	
ABA-463276	Mercedes-AMG G63		1	
4BA-290689	Mercedes-AMG GT63S 4MATIC+	2020	1	
		TOTAL	15	