VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3412	DATE	2022/5/25	
MANUFACTURE	Mercedes-Benz AG			
	(Japanese Importer : Mercedes-Benz Japan Co,. Ltd.)			
DESCRIPTION OF DEFECT	On certain E-Class (213 platform) and S-Class (222 platform) vehicles with Diesel engine, the coolant pump, which is controlled by vacuum, might have a leakage between the vacuum system and the coolant circuit. In this case, ingress of coolant into the vacuum system might damage various components. Should electrical switch valves come in contact with coolant, amongst other things the temperature of the respective parts might in isolated cases increase over time due to an electrochemical reaction. Subsequently, a risk of fire cannot be fully excluded.			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
LDA-213004C	E-Class Sedan		661
LDA-213204C	- E-Class Wagon	2019	416
LDA-213217			391
LDA-222034	- S-Class Sedan	2020	310
		2021	287
LDA-222134		2020	99
		2021	16
LDA-222035		2020	103
		2021	95
LDA-222135		2020	42
		2021	5
		TOTAL	2,425