VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No. Gai-	i-3439	DATE	2022/6/30		
MANUFACTURE Men	Mercedes-Benz AG				
(Јар	(Japanese Importer : Mercedes-Benz Japan Co,. Ltd.)				
DESCRIPTION OF DEFECT platf cont circuin the Short temp	On certain GLE, GLS (167 platform), E-Class (213 platform), S-Class (223 platform), CLS (257 platform) and G-Class (463 platform) vehicles with Diesel engine, the coolant pump, which is controlled by vacuum, might have a leakage between the vacuum system and the coolant circuit. In this case, ingress of coolant into the vacuum system might damage various components. Should electrical switch valves come in contact with coolant, amongst other things the temperature of the respective parts might in isolated cases increase over time due to an electrochemical reaction. Subsequently, a risk of fire cannot be fully excluded.				

TVDF	COMMERCIAL	MODEL YEAR	NUMBER OF
TYPE	NAME	RECALLED	VEHICLE
LDA-213004C		2019	1,074
	E220d	2020	476
3DA-213004C	E220d Wagon	2022	133
3DA-213204C			26
LDA-213217	E220d 4MATIC Wagon	2019	652
		2020	176
3DA-213217		2022	29
3DA-167123	GLE400d 4MATIC	2020	352
3DA-167323	GLE400d 4MATIC Coupe		2
		2021	1
			1
3DA-257314	CLCOOCL	2022	152
3DA-257314C	CLS220d		1
3DA-223033	S400d 4MATIC	2021	1
3DA-167923	GLS400d 4MATIC	2020	909
		2022	1
3DA-463349	G350d	2019	4
		2020	5

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
3DA-463349	G350d	2021	20
3DA-463350	G400d		52
		TOTAL	4,067