VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI 3421	DATE	Jun. 13, 2022	
MANUFACTURE	SCANIA CV AB			
	(Japanese Importer: Bando motors Co. Ltd.)			
DESCRIPTION OF DEFECT	The material of the coolant hose for cooling the retarder does not meet design quality standards, which may cause coolant leakage. Therefore, there is a risk that the coolant warning light to come on, and the vehicle may not be able to run.			

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SCANIA	LPGRS series Truck	2020	15
		TOTAL	15