

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

|                       |  |      |                             |
|-----------------------|--|------|-----------------------------|
| CAMPAIGN No.          | Gai-3416   | DATE | June 6 <sup>th</sup> , 2022 |
| MANUFACTURER          | BMW (Japanese Importer: BMW Group Japan Corp.)   |      |                             |
| DESCRIPTION OF DEFECT | In specific circumstances, the hazard warning switch on audio/ air conditioning control panel may not be able to be deactivated again after it has been activated. This might be then only possible after the vehicle has "gone to sleep". |      |                             |

| TYPE       | COMMERCIAL NAME   | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|------------|-------------------|---------------------|-------------------|
| ZAA-32AW89 | 「BMW i4 M50」      | 2021                | 30                |
|            |                   | 2021                | 12                |
| ZAA-72AW44 | 「BMW i4 eDrive40」 | 2021                | 4                 |
|            |                   | 2021                | 7                 |
|            |                   | TOTAL               | 53                |