

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3461	DATE	August 22, 2022
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	A manufacturing defect may have occurred in the production process of cells for HV battery, which may lead to a malfunction in the high-voltage battery. In rare cases, this can lead to discharge of the cell and in the worst case to a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-72AW44	「BMW i4 eDrive40」	2021	4
ZAA-32AW89	「BMW i4 M50」	2021	1
		2021	1
ZAA-22CF89A	「BMW iX xDrive50」	2021	2
		2021	3
		TOTAL	11