

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI -3460	DATE	16/08/2022
MANUFACTURE	MORGAN MOTOR COMPANY (Japanese Importer :SCI Limited)		
DESCRIPTION OF DEFECT	Due to installation of substandard components in some brake master cylinders, fitted to the cars listed below, some master cylinders have failed leading to a loss of brake pressure and, in a worst case scenario, a possible loss of braking. Thus the system does not conform to Safety Regulation 12.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
MORGAN	PLUS FOUR	2020~2021	26
	PLUS SIX	2019~2021	22
		TOTAL	48