

Recall Notification Form

1th August 2022

Dear Ministry of Land, Infrastructure, Transport and Tourism

Name of Reporter: BMW Japan Corp.

Name of CEO: Christian Wiedmann

Address: 1-9-1 Higashi Shinbashi, Minatoku, Tokyo

Recall Number	Gai-3451	Start of Recall	1st August 2022
Structures, devices or devices that are recognized as non-conforming to the standards. And its causes.	Due to a manufacturing error at the supplier a small number of injectors may not fully close its valve which resulting in a rough engine operation and increased emissions.		
Details of improvement measures	Using the workshop OBD diagnostic equipment run the engine miss-fire and the fuel pressure retention test and replace any injectors that fail either of the tests to injectors which measures have been made.		
Method to inform automobile users and automobile specific maintenance companies	User: Inform by calling or visiting. automobile specific maintenance companies: We know all the users. Thus we will not announce. The recall will be updated on our company webpage.		

Car Name	Type Approval	Common Name	VIN of Recall vehicle and its production period.	Number of Recall Cars	Remark
Rolls-Royce	7BA-665C	Wraith	SCAXZ8100MU208354-SCAXZ8106NU212152 14/07/2021- 14/03/2022	7	
		Dawn		5	
	Total: 1 Type Approval	Total: 2 Valiant Car	(Range of whole production Period.) 14/07/2021- 14/03/2022	Total	12