

Form No. 4: Summary of Recall Campaign in English (Related to Article 2)**Vehicle Safety/Pollution Recall Campaign in Japan**

Import Vehicles

Campaign No.	Gai-3478	Date	Oct. 25, 2022
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	Incorrect specification tailgate lamp assemblies may have been installed resulting in part of the rear turn signal indicator not being illuminated correctly. Inspect / Replace the tailgate lamp assemblies.		

Type	Commercial name	Model year recalled	Number of vehicles
3BA-DC2XC	F-PACE	2021	81
3CA-DC2NC		2021 - 2022	76
7BA-DC5SC	F-PACE SVR	2021	15
Total			172

(JIS A4 size)