## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	Gai-3488	DATE	October 24 <sup>th</sup> 2022
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The third-row seat may not have been produced according to specifications and the compression spring, which locks the backrest, may have not been installed properly or may be missing. In this case, the seat backrest may not be fully locked. In an accident situation or in the event of heavy braking process, load slipping in the luggage compartment may increase the risk of injury.		

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
3DA-CW30	「BMW X7 xDrive35d」	2019 - 2020	3
		TOTAL	3