

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

| | | | |
|-----------------------|--|------|-----------------|
| CAMPAIGN No. | Gai – 3477 | DATE | 5 October, 2022 |
| MANUFACTURER | Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK) | | |
| DESCRIPTION OF DEFECT | Due to a software error in the instrument cluster, the brake booster malfunction symbol is not displayed in accordance with local legal requirements on the affected vehicles in the event of a fault. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|------------|--|------------------------|----------------------|
| 3BA-982M40 | 718 Cayman GTS 718 Boxster GTS | 2020-2022 | 346 |
| 7BA-982M40 | 718 Cayman GTS 718 Boxster GTS | 2020-2022 | 354 |
| 3BA-992L30 | 911 Carrera 911 Carrera S 911 Carrera 4 911 Carrera 4S 911 Targa 4 911 Targa 4S | 2020-2022 | 3101 |
| 3BA-992M38 | 911 Turbo 911 Turbo S | 2020-2022 | 380 |
| 3BA-992NA1 | 911 Carrera 911 Carrera S | 2020-2022 | 63 |
| 3BA-992NA2 | 911 Carrera 4 911 Carrera 4S 911 Targa 4 911 Targa 4S | 2020-2022 | 24 |
| 3BA-992NE | 911 Turbo 911 Turbo S | 2020-2022 | 17 |
| 7BA-992ME | 911 Turbo 911 Turbo S | 2020-2022 | 14 |
| 7BA-992NC1 | 911 Carrera GTS | 2020-2022 | 1 |
| | | Total | 4,300 |