

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3508	DATE	November 2, 2022
MANUFACTURER	Audi (Japanese Importer: VOLKSWAGEN Group Japan K.K.)		
DESCRIPTION OF DEFECT	Due to the improper software, in certain conditions occurring rarely, the seat belt monitoring system in the instrument cluster does not display the actual seat belt status of the occupants correctly and may not give acoustic warning signals if passengers are not wearing their seat belts.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-GBDAD	Audi A1 35T cod	2022	15
3BA-GBDKL	Audi A1 25T	2022	310
3BA-GBDKR	Audi A1 CC 30T	2022	90
		Total	415