

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3505	DATE	2022/11/1
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	On certain E-Class (213 platform), E-Class Coupe/Cabriolet (238 platform), CLS (257 platform) and AMG GT 4-door (290 platform) 4-wheel-drive the transmission wiring harness might not be routed according to specifications. In this case, the mechanical load on the single-wire seal of the transmission wiring harness could lead to a separation in the seal of the electrical connector. As a result, water from the roadway or environment could penetrate the connector. The presence of water could herby create a creeping short circuit if the vehicle is parked. As a result, the short circuit could lead to thermal overload for a longer period of time. Subsequently, the risk of fire cannot be ruled out.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
4AA-257361	Mercedes AMG CLS53 4MATIC+	2022	23
4AA-213061	Mercedes AMG E53 4MATIC+		13
4AA-213261	Mercedes AMG E53 4MATIC+ Wagon		21
4AA-238361	Mercedes AMG E53 4MATIC+ Coupe		1
4AA-238461	Mercedes AMG E53 4MATIC+ Cabriolet		1
4AA-290659	Mercedes AMG GT43 4MATIC+		13
4AA-290659C			4
4AA-290661	Mercedes AMG GT53 4MATIC+		16
			TOTAL