VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

			Boilicotion illipol e veriloico	
CAMPAIGN No.	Gai-3506	DATE	2022/11/1	
MANUFACTURE	Mercedes-Benz AG			
	(Japanese Importer : Mercedes-Benz Japan Co,. Ltd.)			
DESCRIPTION OF DEFECT	On certain GLC (253 platform) 4-wheel-drive vehicles, the routing of the transmission wiring harness might not meet specifications.			
	In these vehicles, mispositioning of the transmission wiring harness could result in chafing with the front drive shaft. Over time, such chafing could potentially result in loss of vehicle propulsion while driving. Additionally, local legal requirements might not be met.			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
5LA-253953	GLC350e 4MATIC	2020	9
		2021	8
		2022	2
5LA-253353	GLC350e 4MATIC Coupe	2020	58
		2021	6
		TOTAL	83