

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-3545	DATE	December 22, 2022
MANUFACTURE	Automobiles PEUGEOT (Japanese Importer :Stellantis Japan Ltd.)		
DESCRIPTION OF DEFECT	On affected vehicles, under engine protector may allow debris to collect in the undercarriage of the vehicle under certain driving conditions. If an excessive amount of debris collects in the undercarriage, it could be in contact with the exhaust pipe that can get very hot and could ignite the debris, causing an underbody fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-K9PYH01	「RIFTER」	2020-2021	769
Unkown	「RIFTER」	2019	221
		TOTAL	990