

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3551	Date	January 19, 2023
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Due to the improper software, in certain conditions occurring rarely, the seat belt monitoring system in the instrument cluster does not display the actual seat belt status of the occupants correctly and may not give acoustic warning signals if passengers are not wearing their seat belts.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-C1DKR	VW T-CROSS 1.0/85kW	MY2022	3,530
		Total	3,530