

第4号様式(英文リコール概要書) (第2関係)

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	外-3544	DATE	2023/1/11
MANUFACTURER	FENDT (Japanese Importer :MSK Farm Machinery Corporation CEO Saito Yoshiyuki)		
DESCRIPTION OF DEFECT	In the engine of agricultural tractor, the engine controller may not function correctly to control engine output. Therefore if the vehicle is used as it is, the engine output may not be controlled correctly in case it is required and the engine may fail consequently. We will check the error history and program the engine controller with the correct software.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
F1050G2	F1050G2	2020	2
		TOTAL	2

(日本工業規格A列4番)