VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic (Import Vehicles)

CAMPAIGN No.	GAI-3483	DATE	November xx, 2022
MANUFACTURE	Indian Motorcycle		
	Polaris Japan Inc		
DESCRIPTION OF DEFECT	Indian Motorcycle has determined that Model Year 2019-2020 and 2022 FTR motorcycles may experience a failure at the coolant junction resulting in coolant loss during operation. If this occurs, coolant may come in contact with the rider, posing an injury hazard and/or coolant may come in contact with the rear tire, posing a crash hazard. To address this concern, Indian Motorcycle has released this safety recall with instructions to replace the coolant junction with an improved part.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
精査中	FTR1200 FTR1200S FTR1200 Rally FTR1200 Carbon FTR1200 R carbon FTR1200 Race Replica	2019~2020, 2022	精査中
		TOTAL	精査中