

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3575	DATE	March 7, 2023
MANUFACTURER	ALPINA Brukard Bovensiepen GmbH + Co. KG (Japanese Importer: Nicole Racing Japan LLC)		
DESCRIPTION OF DEFECT	In the case of some diesel vehicles, EGR (Exhaust-Gas-Recirculation) cooler could become leaky over time. The glycol-leakage in combination with typical soot deposits and the high temperatures normally present in the EGR module, might result in smoldering particles. This could lead in very rare cases to the melting of the intake manifold and in extremely rare cases result in a possible fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-LU20	ALPINA XD3	2019-2021	112
7DA-MU30	ALPINA XD4	2020-2022	35
FDA-5U20	ALPINA D5 S	2018-2019	85
3DA-5U20	ALPINA D5 S	2019-2020	54
		TOTAL	286