

CHILD RESTRAINT SYSTEM RECALL CAMPAIGN IN JAPAN

Domestic/Import Items

CAMPAIGN No.	SOUGAI-11	DATE	April 20, 2023
MANUFACTURER	Ningbo Youying Baby Product Co., Ltd.		
DESCRIPTION OF DEFECT	Due to improper assemble of belt of the top tether belt length adjuster, tension indicator was hidden the belt. As a result, the tension indicator for checking the looseness of the top tether belt cannot be seen, and it may not be installed correctly on the vehicle.		

COMMERCIAL NAME	TYPE	CLASSIFICATION	MODEL YEAR RECALLED	NUMBER OF ITEMS
Nosette Long	DS25	G0+/ I / II	2023	88
			TOTAL	88 units