VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3617	DATE	June. 28 th , 2023
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF	Due to inappropriate instruction for BDC replacement, the replacement rework at dealership was carried out without vehicle data reset.		
DEFECT	As a result, ADL default setting is not correct in vehicles with BDC replaced and therefore does not comply with the Japanese Safety regulation (Article 18 paragraph2 and 3).		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-6L20	BMW 320d xDrive Touring	2022	1
3BA-12AV20	BMW 420i	2021 - 2022	6
3DA-32AX20	BMW 420d xDrive	2022	2
ZAA-72AW44	BMW i4 eDrive40	2022	13
		TOTAL	22