

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3630	DATE	2023/6/22
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On certain S-Class (223 platform) vehicles, the voltage converter software of the secondary on-board electrical system might not meet specifications. In this case, the battery of the secondary on-board electrical system could be discharged after using a diagnostic tool during a workshop visit. As a consequence functions of the ESP and ABS could be impaired. This could increase the risk of an accident. Furthermore, legal requirements might not be met.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
3DA-223033	S400d 4MATIC	2021	754	
		2022	2	
3DA-223133		2021	218	
5AA-223063	S500 4MATIC	2021	1,454	
		2022	1	
5AA-223163		2021	1,512	
4AA-223076	S580 4MATIC	2022	3	
4AA-223176			4	
7AA-223976	Mercedes-Maybach S580 4MATIC		3	
7BA-223979	Mercedes-Maybach S680 4MATIC		4	
-223979-			2	
			TOTAL	3,957