## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

		-		
CAMPAIGN No.	Gai-3607	DATE	2023/5/11	
MANUFACTURE	Mercedes-Benz AG			
	(Japanese Importer : Mercedes-Benz Japan Co,. Ltd. )			
DESCRIPTION OF DEFECT	On certain E-Class (213 platform) and G-Class (463 platform) vehicles with Diesel engine, the coolant pump, which is controlled by vacuum, might have a leakage between the vacuum system and the coolant circuit. In this case, ingress of coolant into the vacuum system might damage various components. Should electrical switch valves come in contact with coolant, amongst other things the temperature of the respective parts might in isolated cases increase over time due to an electrochemical reaction. Subsequently, a risk of fire cannot be fully excluded.			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
3DA-463349	G350d	2019	2
3MA-213016C	E350de	2020	1
	·	TOTAL	3