VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

_				
	CAMPAIGN No.	Gai-3621	DATE	August. 16 th , 2023
	MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
	DESCRIPTION	The affected vehicles possibly have an inadequate laser weld seam on the seat frame of the driver's seat or front passenger seat. As a result, the stability of the seats and therefore the safety of the occupants might not be guaranteed in certain accident situations.		
	OF			
	DEFECT			
		-		

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-5F20	BMW 320i	2021	1
		TOTAL	1