

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3665	DATE	Aug. 8th, 2023
MANUFACTURER	ALPINA Bruckard Bovensiepen GmbH + Co. KG (Japanese Importer: Nicole Racing Japan LLC)		
DESCRIPTION OF DEFECT	On affected diesel vehicles, EGR (Exhaust-Gas-Recirculation) cooler could become leaky over time due to insufficient durability. The glycol-leakage in combination with typical soot deposits and the high temperatures normally present in the EGR module, might result in smoldering particles. This could lead in very rare cases to the melting of the intake manifold and in extremely rare cases result in a possible fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
FDA-3P10	D3 Biturbo	2015-2019	264
	D3 Biturbo Touring	2015-2019	91
	D4 Biturbo Coupe	2016-2019	85
FDA-PP10	XD3 Biturbo	2016-2018	102
3DA-LU20	XD3	2020-2022	112
7DA-MU30	XD4	2021-2024	53
FDA-MP20	D5 Turbo	2014-2017	293
FDA-5U20	D5S	2020-2021	85
3DA-5U20		2021-2022	54
		TOTAL	1139