

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3687	DATE	2023/9/28
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	<p>On certain S-Class (223 platform) right-hand drive vehicles a bolt connection in the engine compartment main fuse box might not meet specifications.</p> <p>This could lead to an increase of the electrical contact resistance at this connection point. As a result, an increase in temperature and thus a fire hazard cannot be completely ruled out. Should the connection be interrupted, the vehicle could lose propulsion while driving. This would increase the risk of a crash and legal requirements might not be met.</p> <p>Furthermore, an influence on the exhaust emissions cannot be ruled out.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-223033	S400d 4MATIC	2021	38
		2022	58
3DA-223133	S500 4MATIC	2021	13
5AA-223063			242
		2022	187
5AA-223163		2023	6
	S580 4MATIC	2021	128
2022		49	
		83	
4AA-223076	S580e 4MATIC	2022	108
4AA-223176			23
5LA-223169	Mercedes-Maybach S580 4MATIC	2023	1
7AA-223976		2022	44
		TOTAL	980