

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai – 3667	DATE	30 November, 2023
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	For the anchor bolts which secure seat belts for left and right sides rear seats, it is possible that they were not tightened due to inappropriate instruction on rework. If the lower rear outboard seat belt anchor screw loosens over time, in the event of a crash, the seatbelt anchor could detach from the affected seat, increasing the risk of an injury.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-J1M20	Macan	2020-2021	1
ABA-G2J30A	Panamera 4		1
		Total	2