## Form No. 4: Summary of Recall Campaign in English (Related to Article 2)

## Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

| Campaign No.          | Gai-3718   | Date | Nov. 21, 2023 |  |
|-----------------------|--|------|---------------|--|
| Manufacturer          | Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited   |      |               |  |
| Description of defect | Jaguar I-PACE vehicles where the High Voltage Coolant Heater (HVCH) can fail to operate. Where the HVCH fails coolant cannot be heated and the windscreen will not be defrosted.  Replacing the Heater Module. |      |               |  |

| Туре      | Commercial name | Model year recalled | Number of vehicles |
|-----------|-----------------|---------------------|--------------------|
| ZAA-DH1AA | I-PACE          | 2020-2022           | 47                 |
| ZAA-DH1CA |                 | 2022                | 10                 |
|           |                 | 2020-2022           | 57                 |

(JIS A4 size)