

**Form No. 4: Summary of Recall Campaign in English (Related to Article 2)****Vehicle Safety/Pollution Recall Campaign in Japan**

Import Vehicles

Campaign No.	Gai-3729	Date	Dec. 14, 2023
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	Due to improper software update by Non-designated tool, Gai-3647 repair was not done correctly.  Update to the Battery Energy Control Module (BECM) software with correct tool.		

Type	Commercial name	Model year recalled	Number of vehicles
ZAA-DH1AA	I-PACE	2019-2022	133
ZAA-DH1CA			43
		2019-2022	176

(JIS A4 size)