

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3725	DATE	2023/12/13
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	<p>On certain SL (232 platform) vehicles with M177 engine the routing of the 12V-starter/generator wiring harness might not meet specifications.</p> <p>In this case, the wiring harness could chafe on the drive shaft. As a consequence, a short circuit, which could potentially result in a loss of propulsion, cannot be ruled out. This might increase the risk of a crash. Additionally, due to the high electrical currents potentially flowing through this connection, the temperature in this area might increase. Therefore, a risk of fire cannot be ruled out completely.</p> <p>Legal requirements might not be met. Additionally, due to the potential deactivation of the start-stop-function resulting from a short circuit, an influence on the exhaust emissions cannot be ruled out.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7BA-232481C	Mercedes-AMG SL63 4MATIC+	2023	143
		TOTAL	143